

**DOT Specification 3AL
Aluminum Alloy 6351-T6
Cylinder Ruptures
United States
Revised 4/13/00**

No.	Incident Date	Incident Location	Service
1	May 1993	Wonderlake, IL	SCBA
2	June 1994	Miami, FL	SCUBA
3	September 1994	Gaithersburg, MD	Medical "O ₂ "
4	March 1995	Bellville, IL	CO ₂
5	July 1996	Morristown, NJ	SCBA
6	July 1996	Union City, GA	Medical "O ₂ "
7	October 1996	Neshanic, NJ	SCBA
8	September 1997	Kalamazoo, MI	SCBA
9	February 1998	Riveria Beach, FL	SCUBA
10	December 1998	Tampa, FL	SCUBA
11	May 1999	Summerfield, NC	SCBA
12*	March 2000	Key Largo, FL	SCUBA

Table Notes:

1. Reported as failure during filling
2. *Information being confirmed
3. SCBA, (Self Contained Breathing Apparatus)
4. SCUBA, (Self Contained Underwater Breathing Apparatus)